

## SVQ Level 3 – Occupational Work Supervision (Construction)

**SCQF overall credit:** Minimum 100 Maximum 114

To attain the qualification candidates must complete **8** units in total. This comprises:

- ◆ 6 mandatory units
- ◆ 2 optional units

Please note the table below shows the SSC identification codes listed alongside the corresponding SQA unit codes. It is important that the SQA unit codes are used in all your recording documentation and when your results are communicated to SQA.

**Mandatory units: Candidates must complete all 6 units from this group**

| SQA code | SSC code    | Title  | SCQF level | SCQF credits |
|----------|-------------|--|------------|--------------|
| HL7P 04  | COSVR209 v2 | Confirm work activities and resources for the work                         | 6          | 18           |
| HL7Y 04  | COSVR210 v3 | Develop and maintain good working relationships                            | 6          | 8            |
| HL7N 04  | COSVR211 v2 | Confirm the occupational method of work                                    | 6          | 14           |
| J3ND 04  | COSVR212 v3 | Implement and maintain health, safety, environmental and welfare practices | 7          | 14           |
| J3NE 04  | COSVR213 v3 | Co-ordinate and organise work operations                                   | 7          | 14           |
| J3NF 04  | COSVR215 v3 | Monitor progress against work schedules                                    | 6          | 10           |

**Optional Units: Candidates must complete 2 units from this group**

| SQA code | SSC code    | Title   | SCQF level | SCQF credits |
|----------|-------------|---|------------|--------------|
| J3NG 04  | COSVR214 v3 | Allocate and monitor the use of plant, machinery, equipment or vehicles | 6          | 20           |
| J3NH 04  | COSVR216 v3 | Confirm work meets contractual, industry and manufacturers' standards   | 7          | 16           |
| J3NJ 04  | COSVR217 v3 | Implement procedures to support team performance                        | 8          | 13           |
| J3NK 04  | COSVR218 v3 | Co-ordinate and confirm the dimensional requirements of the work        | 7          | 9            |